

Photo Album

Colorado County Interior Restoration

2012 – 2013

Part 1



1890 Courthouse



After the 1909 Storm

2008







Removal of paint from brick & cornices
195's office space additions





Completion of Exterior Restoration



1st Floor Railing enclosed for protection



A photograph showing a staircase with dark treads and light-colored risers. A wooden enclosure made of plywood panels is built around the stairs, particularly on the left side. The enclosure has a white-painted top rail. The background shows a wall with dark horizontal paneling and some visible ceiling joists.

Staircase enclosed for protection

Beginning Demolition - Basement



Basement – Bracing & Damaged Floor Joist



Basement Support Beam



A photograph of a ladies restroom in a basement during renovation. The ceiling is exposed, showing wooden joists and insulation. The floor is covered in debris, including torn drywall and insulation. The walls are made of tan tiles. In the foreground, there is a white bathtub. To the left, a red stall door is visible. In the center, there is a red sink counter with two sinks. To the right, there are three white toilets. A black grab bar is mounted on the wall between the middle and right toilets. The overall condition is one of significant disrepair and ongoing work.

Ladies Restroom - Basement





Men's Restroom - Basement



Men's Restroom - Basement

**Portion of concrete support removed, possibly
used to support weight of safe on 1st Floor.**

Basement – Cement Floor Cut for Piping





New Plumbing – Restrooms - Basement



Walls for Restroom



Sewage Ejector



Hole for Sewage Ejector- Basement



Hole – Hand Dug 4'X9'



Sewage Ejector Installed



Support Beam Added



Basement Floor Joists Strengthened



West Basement Stairway Removed



East Basement Stairway Removed





A photograph showing a concrete staircase leading upwards. The stairs are made of grey concrete with dark grey treads. On the left side of the stairs, there is a vertical yellow wall or panel. A small white object with a red cap, possibly a bottle, sits on one of the treads near the top. The background shows a plain, light-colored wall.

Basement Stairway – East Side



1st Floor Hallway

County Judge's Office/County Courtroom



Ceiling – County Courtroom



County Courtroom



A photograph showing the interior of a county courtroom during renovation. The room features high ceilings with exposed wooden beams and several pendant lights. Large windows with dark frames are visible on the left and right walls. In the foreground, a large, dark, curved object, possibly a piano or a piece of furniture, is covered with a dark protective tarp. Two red aluminum ladders are standing in the room; one is leaning against a wall near the windows, and the other is positioned in the center. A worker wearing a white hard hat and dark clothing is sweeping the floor near the windows. The floor is made of large, light-colored tiles. The overall atmosphere is one of active construction or renovation.

County Courtroom



Supports added to County Courtroom ceiling joists.



Window to Door to Window




Window to Door to Window



A photograph showing two construction workers in an underground setting. One worker, wearing a yellow shirt and a white hard hat, is kneeling on the floor, working on a concrete opening. A power tool with a yellow cord is visible on the floor next to him. Another worker, wearing a red shirt and blue jeans, is standing behind him, also near the opening. The floor is made of large, light-colored tiles. In the background, there is a wall made of rough-hewn stone or concrete blocks.

**Concreted opening found in County Clerk's
vault to basement vault.**



1 FIRST FLOOR PLAN - RESTORATION
SCALE 2'10" - 1'-0"

WALL PENETRATION SCHEDULE				
OPENING NUMBER	OPENING SIZE	TYPE OF CONSTRUCTION	FIRE DAMPER	REARANGE
P101	12'9" x 12'	NAM		
P102	10'6" x 10'	NAM		
P103	12'6" x 12'	NAM		



Cutting wall for inside ramp entrance.

A photograph showing a wall under construction. A large rectangular opening has been cut into the wall, which is made of yellow drywall. This opening is intended for an "inside ramp entrance". To the left of the opening, there is a dark wooden structure, possibly a door or a set of stairs. The wall above the opening is also yellow drywall, with some markings and arrows visible. The overall scene suggests a building or renovation project.

**North Entrance – wall
cut for inside ramp
entrance**



County Treasurer's Office



A photograph showing a wooden ramp made of light-colored planks. The ramp leads up a vertical brick wall, which is made of reddish-brown bricks. The ramp has a metal handrail on the left side. The ground at the bottom of the ramp is covered in green grass. The overall image is slightly blurry.

Inside ramp



Support for inside ramp located in basement.



Wooden Lathe

